

# Technical Bulletin

TB 10220 | May 2017

## Product Parts affected

Commissioning tool v1.33

## Details

A new commissioning tool v1.33 has now been released.

### Enhancements

- Support for exporting / importing configuration via SD card, ready for new Vigilon Plus panel.
- Connected / disconnecting message now sent to panel
- This version of comm tool only enables VigInsite V1.01 or above, will not enable v1.00

### Fixes

- Devices config page, when using filter option right hand (devices controls) disabled
- Problem with S4-770-S being changed to S4OHS when using change button
- Errors when printing command build labels
- Visual indication only devices must have strobe / VAD enabled
- Labelling of 2 port ASD interfaces
- Corrected issue of not retrieving FPE information on first fitted loop if loop 1 was missing.
- Inserting sectorable interface not maintaining channel sectoring for subsequent or new interface.
- Corrected issue with multiple device insertions at the same location.
- Corrected issues with monitored line labels not initially uploading and being in the wrong order.

## Action

Engineers to upgrade to new version of tool as soon as possible.