

GENT

by Honeywell

Technical Bulletin	TB 10057
---------------------------	-----------------

To: System Integrators, Novar Gent Services	Date: 09/05/2005
	Status: Active
	Type: Gent/SI

Product – Part affected: Xenex false alarm rejection.
Details: There is an option on the xenex panel for false alarm rejection. This looks to see if there is a second fire within 10 seconds of the first. It has been reported that this does not work with all makes of detectors.
Action: False alarm rejection is only guaranteed to work with the 7800 rang of detectors. Other manufacturer's detectors may not operate correctly with this option. The Xenex manual is being changed to make this clear.

Name: Peter Dodge
